

## Simple operation( AR811/AR821 )




AR831




AR811




AR821



- Insert new DC 9V battery into battery compartment.



- Push power button to turn on unit.
- Use laser point to aim the target.
- Press read button for measurement.



- Detail operation please review the operation manual.

General Features & Specifications	AR811	AR821	AR831
Measuring Range	0.30~15m 10inch~50feet	0.30~15m 10inch~50feet	0.30~15m 10inch~50feet
Accuracy	±1%	±1%	±1%
Measure In Imperial / Metric	✓	✓	✓
Dynamic Display	✓	✓	✓
Laser Pointer Aiming	✓	✓	✓
Data Store / Recall Function	✓	—	—
Compute Area And Volume	✓	✓	✓
Sum Of Length	✓	✓	✓
Auto / Manual Shut-off	✓	✓	✓
LCD Backlight Display	✓	✓	✓
Response Time	2s	2s	2s
Measuring Benchmark Setup	✓	✓	✓
Key Sound , Beeps For Wrong Reading And Reading Confirmation	✓	✓	✓
General Characteristics & Packing Information	AR811	AR821	AR831
Power	9V Alkaline Battery	9V Alkaline Battery	4*AAA Alkaline Battery
Product Net Weight	150g	150g	115g
Product Size	180*53*39mm	180*53*39mm	100*54.5*21.5mm
Packing	Blister	Blister	Blister
Standard Quantity Per Carton	40	40	40
Standard Carton Size	49.5*36.8*27.9cm	49.5*36.8*27.9cm	37.4*36.8*26.4cm
Standard Carton Gross Weight	9.66kg	9.66kg	7.6kg